


US EPA ARCHIVE DOCUMENT

1. Incident Name		2. Date Prepared		3. Time Prepared		UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill		07/05/2012		1700			
4. Unit Name/Designators		5. Unit Leader			6. Operational Period :		
Operations Unit/Containment Branch Monitoring Group		Name:		Dan Capone & Joe Victory (START/US EPA)		From:	07/05/2012 0700
		Position:		Operations Section Chief		To:	07/05/2012 1530
7. Personnel Roster Assigned							
Name		ICS Position			DUTY CELL		
Dan Capone		Operations Section Chief					
Joe Victory		Operations Section Chief					
Rex Johnson		Director					
Dan Zahner		Field Team Lead / CBM Team #3					
8. Activity Log							
Activity Area		Morrow Lake Delta				LAT	LAT
						Various	Various
						(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>		EXTENT OF OIL IMPACTED AREA					
		DENSITY OF OIL /SHEEN					
Total Collection Points		NA					
Total Boom Deployed		None					
Activity		<u>Weston/START Containment Branch Monitoring Group (CBM) Team Activity:</u> Morrow Lake/ New Boom Configuration Boom Configuration A <ul style="list-style-type: none"> Brought out and began to install 1100 ft. of boom for configuration A. They did not complete installation. Work was made difficult by shallow water and high temperatures. Boom Configuration B <ul style="list-style-type: none"> Install two 2.5 inch posts in addition to the two posts already in place at the midpoint of the configuration. They attempted to access the area on the upstream end of the configuration but could only get the boat to within approximately 300 ft. Due to the shallow water depth (<1 ft) and the heat they decided not to put in the upper section of boom until after water levels rise. 					
Health and Safety Issues		Work was stopped at 1500 due to high temperatures.					
Comments		Work activity is logged in logbook CBM3.					